

Stormwater Infrastructure Map

Outfall Name: Herring Pond
 Number: 9
 Location: Herringbrook Road / Herring River /
 Bridge Pond

Description / Planned Roadway Maintenance:
 The road drains to a "first-flush" stormwater system installed in 2006. The road is swept and the basin cleaned routinely, Staff has never seen water come out of the outfall.



- | | | |
|---------------------|----------------|-----------------------|
| Road Surface | Hot Mix | Catchbasins |
| Closed | Mixed in Place | Flow Direction |
| Dirt | Paper | Outfalls |
| Driveway | Stone | Pipe Connections |
| Contours 1:5,000 | | Waterbodies |
| | | Eastham Town Boundary |
| | | State Highway |

Data Sources: Town of Eastham Assessors
 Department, Office of Geographic and
 Environmental Information (MassGIS),
 Commonwealth of Massachusetts Executive
 Office of Environmental Affairs
 Massachusetts State Plane - NAD 83m
 For Planning and Analysis Purposes Only
 Prepared: 9/9/09

